



*The Iso-Cart takes nondestructive measurements of contaminated material without disturbing the waste.*

PD01-0361-13

# *Discovery on Wheels*

## **ISO-CART™ Gamma Spectrometer System**

**B**efore removing old sewage piping beneath Auxiliary Reactor Area (ARA)-23, surface soils needed to be excavated. To safeguard against the spread of possible contamination and to protect workers, Waste Area Group 5 at ARA-23 project managers needed to analyze the soils surrounding the sewer pipes

to determine the level of possible contamination. In FY 2001, the **ISO-CART™ Gamma Spectrometer System** provided the project with an accurate method of performing in situ field gamma measurements in the soil. Using its highly sensitive detectors and analyzer, the ISO-CART™

*Continued on back*

*The ISO-CART™ Gamma Spectrometer System provides an accurate method of performing in situ field gamma measurements in the soil.*

*Continued from front*

takes non-destructive measurements of contaminated material without disturbing the waste. The readings are transmitted to a laptop computer and displayed in either two- or three-dimensional maps and pictures. The adjustable cart positions the detector to obtain accurate readings. Relying on the ISO-CART's™ user-friendly features, workers can use it in a variety of situations. Because the cart holds the entire detector system and is remotely controlled, it reduces the operator's exposure to contaminated material. The **ISO-CART™ Gamma Spectrometer System** is designed for reliable operation in harsh environmental conditions and is simple to operate and easy to maneuver.

*The Iso-Cart is designed for reliable operation in harsh environmental conditions.*

### Benefits:

- Accelerates schedule with faster analytical results
- Reduces worker exposure to contaminated material
- Avoids sampling and disturbing waste and minimizes spread of contamination
- Increases worker safety through remotely-controlled operation



*Two versions of the Iso-Cart. The Iso-Cart used at ARA-23 is on the right.*

*Iso-Cart is confirming a suspect contamination source.*